


G.W.P. AG – How-we-do-business





No.	Alternative Steps	No.	Main process steps	Estimated time	comments
		6	Preparation of mold drawings (G.W.P. China)	3-5 business days	
		7	Confirmation of the mold drawings by the customer		
		8	Mold production (G.W.P. China)	30-40 business days	
		9	Mold testing and production of first shot samples (G.W.P. China)	5-10 business days	
prob In a 10a co cau:	ecessary analysis of the technical blems and corrective action plan. case that the first samples are not onfirmed, G.W.P. analyses the root ses of the stated problems and sets an action plan with corrective and preventive means.	10	Shipment of the first samples including sample inspection report Complete payment of the molds	7 business days	
		11	Confirmation of the samples and order of mass production goods The customer confirmes the samples and sends an official order for the first series.		



